

**2008 Historic Resource Survey
North Side, City of Granbury**

**Property No.: 117
500 East Moore**

Preservation Priority:

Low

These properties have no association or unidentified association with history or historic context(s). They have been moderately to severely altered, losing their original character and architectural integrity. These resources usually do not meet National Register criteria or criteria to be designated as Recorded Texas Historic Landmarks.

Construction Date:

Circa 1880s to 1900



Resource Type/Subtype:

Building/House

Current Owner(s):

C.B. Buchanan and C.H. Ficke

Stylistic Influence:

National Folk, hall and parlor

Brief History:

One of last vestiges of North Side's rural past—plans call for this house to be demolished and a new housing development be built on 13 acres surrounding it just east of Granbury cemetery

Area(s) of Significance:

Description of Resource:

Frame construction, asbestos siding
Gable roof, composition shingles
Double-hung, wood windows
Single-door primary entrance
Shed roof porch, wood posts
Center passage plan
Pier and beam foundation
One story, 1,190 square feet

Integrity:

Location, setting

Possible Threats:

Neglect, development, vacancy

Existing Historical

Designations/Protections:

None