



Media Contact:

Alex Southern, PIO
City of Granbury
817-573-6764 (office)
817-565-5285 (cell)
asouthern@granbury.org

NEWS RELEASE

For Immediate Release

March 2, 2021

Work on Loop 567, FM 51 Intersection Rescheduled for Tuesday, Wednesday

Granbury, Texas – Granbury and Hood County drivers that use the intersection of Loop 567 and Farm to Market Road 51 should be on the lookout for Texas Department of Transportation flaggers directing traffic through the junction from 7 a.m. to 5 p.m. Tuesday and Wednesday, weather-permitting.

Crews working on Loop 567 are performing full-depth pavement repairs as needed. This work includes crews tearing out old road surfaces and digging down approximately eight inches, repairing the roadbed, and adding new asphalt. TxDOT encourages driver attention to all warning signs within the work zone as teams complete this work as quickly and safely as possible.

For further questions or more information, please contact Bethany Kurtz at bethany.kurtz@txdot.gov or 817-730-6744.

--###--